DRAWING REGISTER
Job Ref:

BG

Job No:
201002

ISSUE SHEET

BUTLER GALLERY

McCullough Mulvin
Architects

1 SETANTA PLACE
Dublin 2
Telephone : 0 1 - 707 9555
Fax : 0 1 - 707 1912
Email : info@mcculloughmulvin.com

DISTRIBUTION	
KILKENNY COUNTY COUNCIL	X
CLIENT - BUTLER GALLERY	
MCM FILE	X

2010	DAY	23
	MONTH	9

PRINTS	
CD	
Email	x

DRAWING NUMBER	SIZE	SCALE	DESCRIPTION	PART 8
P SERIES				
P001b	A3	1/ 1000	Proposed Site plan	x
P010	A3	1/ 400	Perimeter Wall Restoration/conservation	x
P100J	A3	1/ 400	Proposed Ground Floor plan	x
P101J	A3	1/ 400	Proposed First Floor Plan	x
P102G	A3	1/ 400	Proposed Lower Roof Plan	x
P103G	A3	1/ 400	Proposed Roof Plan	x
P150E	A3	1/ 400	Proposed Sections AA , BB, CC	x
P160F	A3	1/ 400	Proposed South East & North West Elevation	x
P161F	A3	1/ 400	Proposed South West & North East Elevation	x
P164a	A3	1/ 400	Works to Evans Home Elevations	x
P300	A3	1/ 100	Proposed Works to Garden	x
P900	A3	NTS	3D Images Sheet 1	x
P901	A3	NTS	3D Images Sheet 1	x
D SERIES				
D001a	A3	1/ 400	Demolitions Site,Ground,First & Roof Plan	x
D101	A3	1/100	Room Demolitions Sheet 1	x
D102	A3	1/100	Room Demolitions Sheet 2	x
D103	A3	1/100	Room Demolitions Sheet 3	x
D104	A3	1/100	Room Demolitions Sheet 4	x
D105	A3	1/100	Room Demolitions Sheet 5	x
D106	A3	1/100	Room Demolitions Sheet 6	x
D107	A3	1/100	Room Demolitions Sheet 7	x
D108	A3	1/100	Room Demolitions Sheet 8	x
D109	A3	1/100	Room Demolitions Sheet 9	x
D110	A3	1/100	Room Demolitions Sheet 10	x
D111	A3	1/100	Room Demolitions Sheet 11	x
D112	A3	1/100	Room Demolitions Sheet 12	x
D113	A3	1/100	Room Demolitions Sheet 13	x
D114	A3	1/100	Room Demolitions Sheet 14	x
D115	A3	1/100	Room Demolitions Sheet 15	x
S SERIES				
D1464-01	A3	1/ 500	SurveySite Plan	x
BG-S-003	A3	NTS	Survey Perimeter Wall Photo Survey	x
BG-S-200	A3	NTS	Survey Photo Sheet 1	x
BG-S-201	A3	NTS	Survey Photo Sheet 2	x
BG-S-202	A3	NTS	Survey Photo Sheet 3	x
BG-S-203	A3	NTS	Survey Photo Sheet 4	x
BG-S-204	A3	NTS	Survey Photo Sheet 5	x
BG-S-205	A3	NTS	Survey Photo Sheet 6	x
BG-S-206	A3	NTS	Survey Photo Sheet 7	x
BG-S-207	A3	NTS	Survey Photo Sheet 8	x
BG-S-208	A3	NTS	Survey Photo Sheet 9	x
BG-S-209	A3	NTS	Survey Photo Sheet 10	x
BG-S-210	A3	NTS	Survey Photo Sheet 11	x
BG-S-211	A3	NTS	Survey Photo Sheet 12	x
BG-S-212	A3	NTS	Survey Photo Sheet 13	x
BG-S-213	A3	NTS	Survey Photo Sheet 14	x
BG-S-214	A3	NTS	Survey Photo Sheet 15	x
BG-S-215	A3	NTS	Survey Photo Sheet 16	x
D1464-02	A3	1/ 200	Survey Site Elevation	x
D1464-03	A3	1/ 200	Survey Site Elevation	x
D1464-04	A3	1/ 200	Survey Site Elevation	x
D1492-01	A3	1/ 200	Survey Floor Plans	x
D1492-02	A3	1/ 200	Survey External Elevations	x
D1492-02	A3	1/ 200	Survey External Elevations	x
D1492-03	A3	1/ 200	Survey Sections	x
D1492-04	A3	1/ 100	Survey Internal Elevations	x
D1492-05	A3	1/ 100	Survey Internal Elevations	x
D1492-06	A3	1/ 100	Survey Internal Elevations	x
D1492-07	A3	1/ 100	Survey Internal Elevations	x
D1492-08	A3	1/ 100	Survey Internal Elevations	x
D1492-09	A3	1/ 100	Survey Internal Elevations	x
D1492-10	A3	1/ 100	Survey Internal Elevations	x
D1492-11	A3	1/ 100	Survey Internal Doors	x
REPORTS				
Archaeological projects	A4		Archaeoogial Test Excavation Report	x
Carrig Conservation	A4		Volume 1 : Architectural Record & Inventory	x
	A4		Volume 1: Appendix 1	x
	A4		Volume 2: External Condition Survey Recommendatio	x
	A4		Volume 2: Addendum Internal Schedule of Defects	x
	A4		Volume 2: Appendix 1	x
	A4		Volume 2: Appendix 2	x
	A4		Volume 2: Appendix 3	x
McCullough Mulvin	A4		Conservation Report	x
O Connor Sutton Cronin	A4		Civil /Structural Engineering Services Report	x